



1. Dénudez les fils de 12,7 mm (1/2 po) ; Pour les fils #20 et 22 torsadés, dénudez 3/8" (9,5 mm)
2. Il n'est pas nécessaire d'effectuer une torsion pré-alable ; maintenez les fils dénudés ensemble en veillant à ce que les extrémités soient égales. Conduisez légèrement les fils tordus
3. Alignez les brins ou les conducteurs effilochés
4. Poussez les fils dans le connecteur et vissez jusqu'à ce que deux torsions soient visibles dans les fils

Répertorié comme un connecteur de fil de type à pression
Température nominale : 105°C (221°F) max
Tension nominale : 600V max. dans le câblage du bâtiment ; 1000V max. dans les luminaires et les panneaux
À UTILISER AVEC UN CONDUCTEUR CUIVRE À CUIVRE

⚠ **WARNING:** Cancer and reproductive harm - www.P65Warnings.ca.gov.
⚠ **ADVERTENCIA:** Cáncer y este dano reproductivo - www.P65Warnings.ca.gov.
⚠ **ADVERTISSEMENT:** Cancer et troubles de l'appareil reproducteur - www.P65Warnings.ca.gov.

1. Desforre los cables 1/2" (12,7 mm); Para cables #20 y 22 trenzados, pele 3/8" (9,5 mm)
2. No es necesario que estén previamente trenzados, sostenga los cables desforrados juntos con las puntas al mismo nivel. Meta un poco los cables trenzados
3. Alinee los cables trenzados o conductores deshila-chados
4. Introduzca los cables en el conector y enrosque hasta que se vean dos trenzas en los cables

Certificado como conector de cables tipo a presión
Temperatura nominal: 105 °C (221 °F) máx
Voltaje nominal: 600 V máximo en el cableado del
edificio; 1000 V máximo en artefactos y letreros
**PARA USARSE CON CONDUCTORES DE COBRE
A COBRE**

WWC-N1-C

EASY-TWIST®

WINGED WIRE CONNECTORS

**SAME GRIP
LESS TWISTS**

Yellow N-Type Wire Connectors

100
Qty/Qte/Ctd

22-10 AWG
Solid & Stranded

EASY TWIST N-TYPE SCREW-ON CONNECTORS
For UL Listed, and CSA Certified*

CIRCULAR MILS	2,570	3,060	7743	8,218	19,587	26,116	32,645	38,004
AWG WIRE COMBINATIONS	4 #22	3 #20	3 #16	2 #14	3 #12	4 #12	5 #12	1 #8 w/ 3 #12 Str
WWC-N1								
WWC-N2								

*For complete listing of wire combinations and voltage ratings, scan QR code or contact Customer Service at 800-321-5847



DO NOT PRINT CYAN
LINE-PLACEMENT ONLY



The colors on the package are CMYK, but they should match the spot colors shown above.

PRECAUTION/ADVERTISSEMENT

Turn off power before installing or removing connectors.

Couper l'alimentation avant d'installer ou de retirer les raccords. / Apague la alimentación antes de instalar o retirar los conectores.

TO BE SOLD ONLY WITH INSTALLATION INSTRUCTIONS

1. Strip wires 1/2" (12.7 mm);
For #20 and 22 stranded, strip 3/8" (9.5 mm)

2. Pre-twisting unnecessary, hold stripped wires together with ends even. Lead stranded wires slightly
3. Align any frayed strands or conductors
4. Push wires into connector and screw on until two twists are visible in wires

Listed as a pressure-type wire connector
Temperature Rating: 105°C (221°F) max
Voltage Rating: 600V max in building wiring
1000V max in fixtures and signs

FOR USE WITH COPPER TO COPPER CONDUCTOR



NSI Industries
800.321.5847
nsiindustries.com



Made in China | Fabrique en Chine | Hecho en China

115mm